


AT-RLM-054



NOTE: USE 0.250 FEMALE QD'S ON MATING WIRES
AND FUSE BATTERY INPUT AT 10 AMPS MAXIMUM